


Safety Behaviours and Electrocution Risks

General Safety*



You need TWO permits: Permit to Enter and Electrical Permit to Work



Use Marker posts to give emergency location



Personnel must be trained or supervised




Person in Charge must brief everyone about Limits of Permit to Work

Electrocution Hazard - you might lose your life!



Do not lift anything above your head when on wagon decks or on loco running boards.



Smoke can conduct electricity




Don't climb on loads and high sided rolling stock under the overhead




Carry long objects lengthways NOT up and down



Stay away from derailed vehicles touching wires. They may conduct electricity.



Do not touch both sides of broken rails or bonds. You may conduct electricity.



Loose or flapping loads on vehicles will conduct electricity or damage overhead wires



Direct water/fluids/CO2 and dry powder down and away from overhead wires



Do not remove anything hanging from the overhead lines.

In case of an emergency call

0800 808 400

*See separate posters for AC and DC safe working distances # Contractors and 3rd Parties