

SIGNALLING & INTERLOCKING ARRANGEMENTS

[illegible]

'40'  ADDITIONAL BOARD ABOVE PERMANENT SPEED BOARD
READING 'THROUGH TURNOUT'

I. D. COTTON
NATIONAL STANDARDS AND RISK MANAGER